OTT HydroMet GmbH | Ludwigstraße 16 | 87437 Kempten | Germany | +49 831 5617-0 | euinfo@otthydromet.com | www.otthydromet.com

Last update: February 17. 2023

Please note:
For WSXXX device versions ≥30 (see serial number)

Get the newest release

Release Notes

V 70 (17.02.2023)

- Bugfix: I2C Driver fix to avoid read problems (timing)from EEPROM
- Feature add: fan monitoring feature added, available since hardware release 32

V 69 (23.08.2022)

- Feature add: Deactivation automatic hardware-switch for SDI12. SDI-12 protocol communication is available now in standard RS485 mode
- Feature add: SDI12 Command aXVd! added to poll for device revision number