

Sealing Supply Only

Use this checklist when sealing supply only.



TASK

- 1 Arrive on job site/Perform a home walk-thru
- 2 Combustion appliances
- 3 Turn off HVAC
- 4 Bring in the equipment
- 5 Block all registers
- 6 Determine and cut injection point
- 7 Isolate HVAC system
- 8 Attach layflat
- 9 Set up HSC
- 10 Open AeroSuite
- 11 Inflate layflat/Perform fog test [FOG IT]

TASK

- 12 Search for fog in home [FIND IT]
- 13 Perform the pre-seal leakage test [FEEL IT]
- 14 Repair major duct damage/disconnects [FIX IT]
- 15 Seal the duct system
- 16 Perform flush and cooldown
- 17 Perform post-seal leakage test/Print certificate [FINISH IT]
- 18 Clean nozzle assembly
- 19 Remove layflat
- 20 Remove blocking and isolation. Return equipment to vehicle
- 21 Restore home to working order

