



For additional information about this product, please scan the QR code provided.

YellowGate 2.0


ISSUE DATE:	July 17, 2024	PART NUMBER:	11792-R2
SUBJECT:	YellowGate 2.0 Troubleshooting	PRODUCT LINE:	YellowGate
TOPIC:	TROUBLESHOOTING YOUR NEW YELLOWGATE 2.0 SAFETY GATE		

OVERVIEW

If the yellowgate hinge assemblies are binding, confirm that the telescoping arm is extended an equal amount from the top and bottom arm. In the figure shown dimensions “**A**” and “**B**” should be equal

If the gate requires a lot of force to open, and/or is not self closing, then dimensions “**A**” and “**B**” are greatly different and the length of the gate should be adjusted. This can be completed by loosening the telescoping clamp bolt and repositioning the telescoping arm in the opening to make the gate square.

If the gate opens easily but does not close when only opened a minimal amount, then dimensions “**A**” and “**B**” are slightly different and small adjustments should be made to either dimension to square up the gate. This can be completed by loosening the telescoping clamp bolt of one clamp and moving the arm in or out slightly. Swing the gate and ensure no binding then tighten the clamp back up. If the hinge assembly is still binding adjust the other direction.



YellowGate 2.0 PN:11792-R2

Reach out to your local yellowgate representative if the above steps do not resolve the issues with the gate.