

**Kubota Canada Ltd. recalls reserve coolant tank caps for various Ride-On Mowers, Utility Tractors and Zero Turn Mowers**

**Affected products**

Coolant tank caps for Kubota Ride-on Mowers, Utility Tractors and Zero Turn Mowers

**Replacement coolant cap**



## Product description

This recall involves model year 2014 to 2018 Kubota BX compact utility tractors, ZD and ZG diesel and gasoline-powered zero turn mowers, and GR ride-on mowers. The model number is printed on the side of the unit. Kubota is printed on the side of the mowers and tractors. The data plate contains the serial number and is also located on the side of the unit. The affected units are orange and black.

The model and serial numbers for the affected products sold in Canada are listed in the table below.

<b>Model</b>	<b>Serial Number Range</b>
GR2120-48	16256 - 16435
GR2120-54	16257 - 16438
GR2120-2-48	30002 - 37086
GR2120-2-54	30001 - 37092
ZD1011-48	10005 - 13256
ZD1011-54	10004 - 13257
ZD1021-60	10004 - 12794
ZD1211-60	10002 - 28308
ZD1211L-72	10002 - 24551
ZD1211R-60R	10002 - 20642
ZD1211RL-72R	10002 - 20454
ZD221-48	33698 - 35859
ZD221-54	33701 - 35861
ZD326P	39440 - 44820
ZD326RP-60R	12065 - 12786
ZD331LP	42720 - 43628
ZD331P	33772 - 33993
ZD331RP-60R	11015 - 11130
ZD323-60	35702 - 37252
ZG332LP-72	10672 - 10737
ZG332P-60	10688 - 10694

BX1870-1	20323 - 26934
BX2370-1	20742 - 51823
BX2670-1	20370 - 50241
BX25D-1	20002 - 52366
BX1880	10002 - 14699
BX2380	10007 - 25496
BX2680	10007 - 16378
BX23S	10005 - 25607

## Hazard identified

Kubota has discovered that under some overheat conditions, the cap of the radiator coolant reserve tank, if restricted, can come off and high temperature coolant may spray out, posing a burn hazard.

As of January 15, 2019, the company has received no reports of incidents or injuries in Canada.

## Number sold

Approximately 17,428 units of the affected products were sold in Canada.

## Time period sold

The affected products were sold from July 2014 to August 2018.

## Place of origin

Manufactured in the United States.

## Companies

<b>Distributor</b>	Kubota Canada Ltd. Markham Ontario Canada
--------------------	--

## What you should do

**Consumers should immediately stop using the recalled Kubota Ride-on Mowers, Utility Tractors and Zero Turn Mowers. Customers are to be mailed a new cap by**

**Kubota Canada along with installation instructions. Consumers may also contact an authorized Kubota dealer for a free inspection and repair of the cap.**

For more information, consumers may contact Kubota Canada Ltd. toll free at 1-800-405-6916 from 8:30 a.m. to 4:30 p.m. ET Monday through Friday, by [email \(CustomerService@kubota.ca\)](mailto:CustomerService@kubota.ca) or online (Kubota to provide a link).

Please note that the Canada Consumer Product Safety Act prohibits recalled products from being redistributed, sold or even given away in Canada.

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the Consumer Product Incident Report Form (<https://www.canada.ca/en/health-canada/services/consumer-product-safety/advisories-warnings-recalls/report-incident-involving-consumer-product.html>).

This recall is also posted on the [OECD Global Portal on Product Recalls website \(http://globalrecalls.oecd.org/\)](http://globalrecalls.oecd.org/). You can visit this site for more information on other international consumer product recalls.

## Model Images

### BX model compact utility tractor



**GR model ride-on mower**



**ZD model zero turn mower**



**ZG model zero turn mower**



**Data plate with model and serial number**



**White coolant reserve tank with a yellow cap**

