



# CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

**SERVICE** BG Dynamic Engine Restoration Service

**PRODUCTS** BG Dynamic Engine Cleaner, PN 103192  
BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GA  
BG Platinum® 44K®, PN 208  
BG Advanced Formula MOA®, PN 115



**VEHICLE:**  
2015 Toyota Tundra  
52,300 miles (84,169 km)

## PROBLEM

No record of an oil change (neglected maintenance).

## SOLUTION

The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

### Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

### Benefits:


- Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency





## SERVICE RESULTS

OIL PUMP PICKUP



TIMING CHAIN



## SUMMARY

The service removed all signs of sludge and oil deposits. The engine is also protected from future deposit buildup and wear and now is covered by the Lifetime BG Protection Plan®!

**Field Case Study submitted by:** LSI of Texas