



CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

SERVICE BG Dynamic Engine Restoration Service

PRODUCTS BG Dynamic Engine Cleaner, PN 103192
BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GA
BG Platinum® 44K®, PN 208
BG Advanced Formula MOA®, PN 115



VEHICLE:
2011 Toyota Tundra
85,523 miles (137,636 km)

PROBLEM

Oil changes extended out to 10,000 miles.

SOLUTION

The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

Benefits:

- Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency





SERVICE RESULTS

CRANKCASE



VALVE COVER



SUMMARY

BG Dynamic Engine Restoration cleaned the crankcase and removed oil sludge and varnish. As a result, this vehicle will last longer and perform better.

Field Case Study submitted by: BG Puerto Rico Caribbean Auto Distributors