



CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

SERVICE BG Dynamic Engine Restoration Service

PRODUCTS BG Dynamic Engine Cleaner, PN 103192
BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GA
BG Platinum® 44K®, PN 208
BG Advanced Formula MOA®, PN 115



VEHICLE:
2009 Ford Flex
178,000 miles (286,463 km)

PROBLEM

Faulty water pump led to a coolant leak in the engine.

SOLUTION

The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

Benefits:


- Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency






SERVICE RESULTS

CRANKCASE



CRANKCASE



SUMMARY

The service removed all signs of the coolant-mixed sludge and the crankcase looks nearly brand new.

Customer Testimonial: The results were amazing!

Field Case Study submitted by: Kansas BG