



CASE STUDY: BG DYNAMIC ENGINE RESTORATION SERVICE

SERVICE BG Dynamic Engine Restoration Service

PRODUCTS BG Dynamic Engine Cleaner, PN 103192
BG Dynamic Engine Cleaner Rinse Oil, PN PE04-N1GA
BG Platinum® 44K®, PN 208
BG Advanced Formula MOA®, PN 115



VEHICLE:
2015 BMW X1, N20 Engine
86,276 miles (138,848 km)

PROBLEM

No oil changes in 4 years/~30,000 miles (neglected maintenance).

SOLUTION

The BG Dynamic Engine Restoration Service: a powerful, safe engine and fuel system cleaning service.

Features

- Removes oil sludge and varnish
- Restores compression
- Harmless to oil pumps, seals, and gaskets

Benefits:

- Lowers tailpipe emissions
- Reduces oil consumption
- Improves overall power and engine efficiency





SERVICE RESULTS

CRANKCASE



SUMMARY

The BG Dynamic Engine Restoration Service erased years of neglect in this vehicle. With proper maintenance moving forward, this vehicle will continue to perform better and last longer.

Field Case Study submitted by: Kansas BG